



## TIG Welder

### Employer

Webster Combustion  
619 Industrial Blvd,  
Winfield, KS 67156

### Job Details

**Job Location:** Winfield

**Job Status:** Hourly

**Schedule:** Full-Time

**Salary Range:** N/A

**Reports To:** Department Supervisor


This full-time position requires the Welder to weld metal parts together according to blueprints, technical layouts, shop drawings, and product order sketches using manual arc, wire, and mig welders. Performs related tasks such as flame cutting and grinding. May be required to repair broken or cracked parts, fill holes and increase size of metal parts. Reports to the Weld Shop Team Lead.

### Responsibilities

- Weld metal parts together using blueprints, layouts and sketches provided by Engineering department
- Will layout metal, set-up, and tack in accordance with welding blueprints, etc before welding
- Use fixtures, jigs, clamps, and other positioning devices commonly used in welding
- Use various power and hand tools as required to complete production welding tasks
- Perform user maintenance on all machines and equipment
- Maintains a neat, clean, orderly, and functional work area at all times
- Checks work area for compliance of all safety rules and standards. Reports any unsafe or uncompliant issues to Team Lead or Operations Manager in a timely manner
- Other duties as assigned

### Requirements

- High School Diploma or equivalent. Welding certification/experience desirable
- Ability to perform Mig, Tig, and Heli-Arc welding tasks
- Ability to read blueprints, technical layouts/sketches

- 
- Ability to follow verbal or written instructions
  - Knowledge and experience using both manual and power hand tools
  - Ability to use manual arc, wire and mig welders.
  - Familiar with fixtures, jigs, clamps and other positioning devices
  - Must be detail oriented
  - Ability to work in a fast- paced environment
  - Ability to work overtime and weekends if required
  - Familiar with working in a warehouse/manufacturing environment

#### **Physical Demands**

- The employee is regularly required to stand; walk; use hands/fingers to handle or feel; reach with hands and arms; climb, ascend/descend or balance to heights that may require a ladder or lift; stoop, kneel, crouch, or crawl in confined spaces; and talk or hear.
- The employee is occasionally required to sit.
- The employee must occasionally lift and/or move more than 50 pounds.
- The employee is occasionally exposed to outside weather conditions and a plant which is not temperature controlled.
- Inside Work is typically performed in a factory environment and is usually very loud.
- In the factory environment, the employee may be exposed to hazardous materials and/or greasy or slippery factory floors.

This Job Description is a guide to the critical duties and essential functions of the Job, not an all-inclusive list of responsibilities, qualifications, physical demands and work environment conditions. Job descriptions are reviewed and revised to meet the changing needs of the company at the sole discretion of management.

#### **Application Instructions:**

Apply [here](#) or

Send resume to HR Manager: [hr@webstercombustion.com](mailto:hr@webstercombustion.com)